

Diagnostic History

The Report is created by **LAUNCH X-431**

Vehicle Information

License #:

Year:2018

Make:Land Rover

Model:Range Rover Velar(L560)

VIN:SALYA2BV1JA723025

Odometer:38464 km

Test Time:2023-12-21 01:02:14AM

Vehicle Software Version:V34.70

Diagnostic Application Version:V7.00.010

User Operation:

> Health Report

> System Selection

> System Selection > ECM (Engine Control Module)

> System Selection > ABS (Anti-Lock Brake System Control Module)

DTC

DTC	Description	State	System
B100D-87	Column Lock Authorisation - Missing Message	Confirmed	BCM (Body Control Module)
U0055-87	Vehicle Communication Bus D - Missing Message	Confirmed	GWM (Gateway Module 'A')
B134C-77	Front Left - Face Damper Motor - Commanded Position Not Reachable	Confirmed	HVAC (HVAC Control Module)
B1359-77	Ignition Run/accessory - Circuit Failure. - Commanded Position Not Reachable	Confirmed	HVAC (HVAC Control Module)
B135D-77	Rear Right - Face Damper Motor - Commanded Position Not Reachable	Confirmed	HVAC (HVAC Control Module)
B1416-15	Left Front Cooled/Heated Seat Thermal Electric Device #2 Temperature Sensor - Circuit Short To Battery Or Open	Confirmed	HVAC (HVAC Control Module)
B100E-64	Video Input A. - Signal Plausibility Failure	Confirmed	IPC (Instrument Panel Cluster Control Module)
B108E-31	Display - No Signal	Confirmed	IPMB (Image Processing Module 'B')
B14A9-13	BroadR-Reach  link - Telematics (+) - Open Circuit	Confirmed	TCU (Telematic Control Unit Module)
B14AA-13	BroadR-Reach  link - Telematics (-) - Open Circuit	Confirmed	TCU (Telematic Control Unit Module)