

Diagnostic History

The Report is created by **LAUNCH** X-431

Vehicle Information

License #:

Year:2018.01

Make:Rolls Royce

Model:Phantom

VIN:SCA687S0XJU104103

Odometer:92688 km

Test Time:2024-05-20 11:47:19PM

Vehicle Software Version:V51.40

Diagnostic Application Version:V7.00.011

User Operation:System Selection > Drive > CAS (Car Access System - CAS/FEM/BDC)

System Selection > Drive > ECM (Engine Control Module - DME/DDE)

System Selection > Drive > ECM2 (Engine Control Module 2 - DME2)

System Selection > Drive > TCM (Transmission Control Module - EGS)

DTC

DTC	Description	State	System
0301B2	Power Window, Passenger's Side, Rear: Fault In Initialisation	Permanent	CAS (Car Access System - CAS/FEM/BDC)
48077E	RDCi: Wheel Electronics, Battery Life, Rear Left	Permanent	ABS (Anti-Lock Braking System - DSC)
48362F	Voltage Supply - Degradation, Undervoltage, External	Intermittent	VOCS (Interior Camera)
48342F	Voltage Supply - Degradation, Undervoltage, External	Intermittent	ARS (Front Electric Active Roll Stabilisation)
031A43	Rear Left Automatic Soft Closing, Drive: Malfunction	Intermittent	CDMSL (Coach Door Module, Left)
806797	SPNMVL: Multiple Fault For Valves And Sensors	Intermittent	SPNMVL (Front Left Seat Inflator Module)
80679C	Seat Pneumatics Module Front Left, Massage Function: Air Cushion, Right, For Active Seat (Valve 4), Nominal Pressure Reached Too Quickly	Intermittent	SPNMVL (Front Left Seat Inflator Module)
031786	TCB: Functional Limitation Of Last State Call	Intermittent	ECALL (Emergency Call)
031782	HU-H: Functional Limitation Of Online	Intermittent	CIC (Car Information Computer)
802C3F	SMBF, Picnic Table Adjustment: Mechanical Locking Detected	Intermittent	BFS (Seat Module, Passenger)
802BC6	Front Passenger Seat Module, Switch Block Seat Adjustment (LIN): Switch Hangs (Continuous Operation)	Intermittent	BFS (Seat Module, Passenger)
483106	VDP: Vehicle Extremely High - Front Left	Intermittent	VDC/VDM (Vertical Dynamics Management)
483104	VDP: Vehicle Extremely High - Front Right	Intermittent	VDC/VDM (Vertical Dynamics Management)
483102	VDP: Vehicle Extremely High - Rear Right	Intermittent	VDC/VDM (Vertical Dynamics Management)
483100	VDP: Vehicle Extremely High - Rear Left	Intermittent	VDC/VDM (Vertical Dynamics Management)
482978	VDP: Maximum Switched-On Period Exceeded	Intermittent	VDC/VDM (Vertical Dynamics Management)