

Diagnostic History

The Report is created by **LAUNCH** X-431

Vehicle Information

License #:

Year:2022.01

Make:BMW

Model:M8

VIN:WBSGV0C01NCJ95102

Odometer:22915 km

Test Time:2024-12-04 01:48:23AM

Vehicle Software Version:V51.40

Diagnostic Application Version:V7.00.011

User Operation:System Selection > Drive > CAS (Car Access System - CAS/FEM/BDC)

System Selection > Drive > ECM (Engine Control Module - DME/DDE)

System Selection > Drive > ECM2 (Engine Control Module 2 - DME2)

System Selection > Drive > LMV/VTG (Transfer Case)

System Selection > Drive > TCM (Transmission Control Module - EGS)

DTC

DTC	Description	State	System
804081	Drive Readiness, Error: Production Not Possible	Intermittent	CAS (Car Access System - CAS/FEM/BDC)
804136	Contactless Vehicle Access Deactivated	Intermittent	CAS (Car Access System - CAS/FEM/BDC)
D90D11	Evaluation Electronics, Contactless Tailgate Opening (LIN): Missing LIN Components Or No Communication Possible	Intermittent	CAS (Car Access System - CAS/FEM/BDC)
138A02	Exhaust Flap 2, Activation: Short Circuit To Ground	Intermittent	ECM2 (Engine Control Module 2 - DME2)
138A04	Exhaust Flap 2, Activation: Open Circuit	Permanent	ECM2 (Engine Control Module 2 - DME2)
420641	Parking Lock: Incorrectly Applied	Intermittent	TCM (Transmission Control Module - EGS)
803185	PDC: Activation Not Possible	Intermittent	SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
8031B9	Voltage Supply, Ultrasonic Sensor Rear: Short Circuit To Ground	Intermittent	PMA (Parking Assistant)
8031F1	Ultrasonic Sensor, PMA, Rear Side Left, Data Line: Short Circuit To Ground	Intermittent	PMA (Parking Assistant)
8031F2	Ultrasonic Sensor, PMA, Rear Side Left, Data Line: Open Circuit	Intermittent	PMA (Parking Assistant)
803202	Ultrasonic Sensor, Rear Outer Left, Data Line: Open Circuit	Intermittent	PMA (Parking Assistant)
803207	Ultrasonic Sensors: Extraneous Noise Detected	Intermittent	PMA (Parking Assistant)
803212	Ultrasonic Sensor Rear Centre Left, Data Line: Open Circuit	Intermittent	PMA (Parking Assistant)
803222	Ultrasonic Sensor Rear Centre Right, Data Line: Open Circuit	Intermittent	PMA (Parking Assistant)
803232	Ultrasonic Sensor, Rear Outer Right, Data Line: Open Circuit	Intermittent	PMA (Parking Assistant)
803242	Ultrasonic Sensor, PMA, Rear Side Right, Data Line: Open Circuit	Intermittent	PMA (Parking Assistant)
803260	Ultrasonic Sensor, PMA, Rear Side Left: Blindness Identified	Intermittent	PMA (Parking Assistant)
803261	Ultrasonic Sensor, Rear Outer Left: Blindness Identified	Intermittent	PMA (Parking Assistant)
803266	Ultrasonic Sensor For PMA, Front Left Side: Blindness Identified	Intermittent	PMA (Parking Assistant)
80337A	Ultrasonic Sensors: Reduced Measurement Frequency Or Incorrect Installation	Intermittent	PMA (Parking Assistant)
801A00	Anti-Theft Alarm System: Ultrasonic Sound Sensor System: One Or Two Channels Are Faulty	Permanent	FZD (Function Center, Roof)

800ABF	KAFAS Camera: Field Of Vision Impaired For A Short Time	Intermittent	KAFAS (Camera Based Driver Assist Systems)
026004	Instrument Panel: Coding: Internal SWT Check Failed	Permanent	IC (Instrument Cluster - INSTR)
026003	Instrument Panel: Coding: External SWT Test Condition Not Met	Permanent	IC (Instrument Cluster - INSTR)
031790	HU-H: Function Restriction Connection Establishment / Coupling Bluetooth	Intermittent	CIC (Car Information Computer)
031791	HU-H: Function Restriction Bluetooth Connection	Intermittent	CIC (Car Information Computer)
03179A	HU-H: Function Restriction Connection Apple CarPlay	Intermittent	CIC (Car Information Computer)
802A1E	SMFA: No Seat Adjustment Is Possible Due To Engine Start	Intermittent	FAS (Seat Module, Driver)
802C1E	SMBF: No Seat Adjustment Is Possible Due To Engine Start	Intermittent	BFS (Seat Module, Passenger)
80132F	Stationary Climate Control: Remote Engine Start Not Possible / Cancellation	Intermittent	AC (Air Conditioning - IHKA)